
MERCEDES 722.6

PART NUMBERS 68942-02, -03, -04, -05K

Overlap Control Valve Sleeve Kits



INSPECTION

Inspect the inside diameter of the overlap control valve sleeves for signs of wear. Shiny patches indicate excessive wear.

- NOTE: Ensure that the OEM springs are returned to their appropriate locations. Location, spring free length, and the spring load at full stroking height of the inner valve are as follows:
- 1-2 Overlap Spring: .817" free length; 1.5 lbs Sleeve: 1 I.D. notch
- 2-3 Overlap Spring: .654" free length; 11.4 oz Sleeve: 2 I.D. notches
- 3-4 Overlap Spring: .790" free length; 1.2 lbs Sleeve: 3 I.D. notches

INSTALLATION

- 1. Remove the OEM sleeve, plunger valve and spring.
- 2. Discard the worn sleeve. Retain the plunger valve and spring.
- 3. Install the o-ring into the sleeve groove and roll on the bench to resize the O.D. Lubricate the o-ring and sleeve.
- 4. Reinstall the spring into the plunger valve pocket. Slide the correct sized plunger valve into the sleeve, with the spring facing the grooved end face. The end-face grooves on the sleeve aid in easy identification.
- 5. Slowly install the sleeve assembly into the valve body bore, taking care not to shear the o-ring. Ensure the end face grooves are outward.



